

Executive Summary – Enforcement Matter – Case No. 48895
The Premcor Refining Group Inc.
RN102584026
Docket No. 2014-0903-AIR-E

Order Type:

Findings Agreed Order

Findings Order Justification:

People or environmental receptors have been exposed to pollutants which exceed levels that are protective.

Media:

AIR

Small Business:

No

Location(s) Where Violation(s) Occurred:

Valero Port Arthur Refinery, 1801 South Gulfway Drive, Port Arthur, Jefferson County

Type of Operation:

Petroleum refinery

Other Significant Matters:

Additional Pending Enforcement Actions: Yes, Docket Nos. 2011-2300-AIR-E, 2013-0839-AIR-E, 2014-0465-AIR-E, and 2014-0630-AIR-E

Past-Due Penalties: No

Other: N/A

Interested Third-Parties: None

Texas Register Publication Date: October 17, 2014

Comments Received: No

Penalty Information

Total Penalty Assessed: \$25,000

Amount Deferred for Expedited Settlement: \$0

Amount Deferred for Financial Inability to Pay: \$0

Total Paid to General Revenue: \$12,500

Total Due to General Revenue: \$0

Payment Plan: N/A

SEP Conditional Offset: \$12,500

Name of SEP: Texas Association of Resource Conservation and Development Areas, Inc. (Third-Party Pre-Approved)

Compliance History Classifications:

Person/CN - Satisfactory

Site/RN - Satisfactory

Major Source: Yes

Statutory Limit Adjustment: \$25,000

Applicable Penalty Policy: April 2014

Executive Summary – Enforcement Matter – Case No. 48895
The Premcor Refining Group Inc.
RN102584026
Docket No. 2014-0903-AIR-E

Investigation Information

Complaint Date(s): N/A
Complaint Information: N/A
Date(s) of Investigation: May 6, 2014
Date(s) of NOE(s): June 11, 2014

Violation Information

Failed to prevent unauthorized emissions [30 TEX. ADMIN. CODE §§ 101.20(3), 116.115(b)(2)(F), 116.115(c), and 122.143(4), TEX. HEALTH & SAFETY CODE § 382.085(b), Federal Operating Permit No. O1498, Special Terms and Conditions No. 18, and New Source Review Permit Nos. 6825A, PSDTX49, and N65, Special Conditions No. 1].

Corrective Actions/Technical Requirements

Corrective Action(s) Completed:

N/A

Technical Requirements:

1. The Order will require the Respondent to implement and complete a Supplemental Environmental Project ("SEP"). (See SEP Attachment A)
2. The Order will also require the Respondent to:
 - a. Within 30 days, implement measures and/or procedures designed to prevent recurrence of emissions events due to similar causes as Incident No. 193520; and
 - b. Within 45 days, submit written certification to demonstrate compliance with Ordering Provision a.

Litigation Information

Date Petition(s) Filed: N/A
Date Answer(s) Filed: N/A
SOAH Referral Date: N/A
Hearing Date(s): N/A
Settlement Date: N/A

Executive Summary – Enforcement Matter – Case No. 48895
The Premcor Refining Group Inc.
RN102584026
Docket No. 2014-0903-AIR-E

Contact Information

TCEQ Attorney: N/A

TCEQ Enforcement Coordinator: Rajesh Acharya, Enforcement Division,
Enforcement Team 4, MC 149, (512) 239-0577; Candy Garrett, Enforcement Division,
MC 219, (512) 239-1456

TCEQ SEP Coordinator: Stuart Beckley, SEP Coordinator, Enforcement Division,
MC 219, (512) 239-3565

Respondent: J. Greg Gentry, Vice President and General Manager, The Premcor
Refining Group Inc., P.O. Box 909, Port Arthur, Texas 77641-0909

Respondent's Attorney: N/A

Attachment A
Docket Number: 2014-0903-AIR-E
SUPPLEMENTAL ENVIRONMENTAL PROJECT

Respondent:	The Premcor Refining Group Inc.
Penalty Amount:	Twenty-Five Thousand Dollars (\$25,000)
SEP Offset Amount:	Twelve Thousand Five Hundred Dollars (\$12,500)
Type of SEP:	Contribution to a Third-Party Pre-Approved SEP
Third-Party Administrator:	Texas Association of Resource Conservation and Development Areas, Inc.
Project Name:	<i>Tire Collection Events and Cleanup of Abandoned Tire Sites</i>
Location of SEP:	Jefferson County: Neches-Trinity Coastal River Basin, Gulf Coast Aquifer

The Texas Commission on Environmental Quality ("TCEQ") agrees to offset a portion of the administrative penalty amount assessed in this Agreed Order for the Respondent to contribute to a Supplemental Environmental Project ("SEP"). The offset is equal to the SEP Offset Amount set forth above and is conditioned upon completion of the project in accordance with the terms of this Attachment A.

1. Project Description

a. Project

The Respondent shall contribute the SEP Offset Amount to the Third-Party Administrator named above. The contribution will be to the **Texas Association of Resource Conservation and Development Areas, Inc. ("RC&D")** for the *Tire Collection Events and Cleanup of Abandoned Tire Sites* project. The contribution will be used in accordance with the SEP Agreement between the Third-Party Administrator and the TCEQ (the "Project"). Specifically, the SEP Offset Amount will be used to coordinate with local city and county government officials and private entities ("Partner Entities") to conduct tire collection events where residents will be able to drop off tires for proper disposal or recycling ("Collection Events"), or to clean sites where tires have been disposed of illegally ("Site Cleanups").

Texas RC&D shall ensure that collected tires, debris, and waste are properly transported to and disposed at an authorized disposal site, and if a licensed hauler is needed for tires or other regulated waste collected from sites, Texas RC&D shall ensure that only properly licensed haulers are used for transport and disposal of tires and regulated wastes. The SEP will be performed in accordance with all federal, state, and local environmental laws and regulations.

The Premcor Refining Group Inc.
Agreed Order - Attachment A

All dollars contributed will be used solely for the direct cost of the Project, including but not limited to supplies, materials, and equipment. Any portion of this contribution that is not able to be spent on the specifically identified SEP may, at the discretion of the Executive Director ("ED"), be applied to another pre-approved SEP.

The Respondent's signature affixed to this Agreed Order certifies that it has no prior commitment to make this contribution and that it is being contributed solely in an effort to settle this enforcement action. The Respondent shall not profit in any manner from this SEP.

b. Environmental Benefit

This SEP will provide an environmental benefit by providing communities with a free and convenient means for safe and proper disposal of tires and by reducing the dangers and health threats associated with illegally dumped tires.

The health risks associated with illegal dumping are significant. Areas used for illegal tire dumping may be easily accessible to people, especially children, who are vulnerable to the physical hazards posed by abandoned tires. Rodents, insects, and other vermin attracted to dump sites may also pose health risks. Tire dump sites which contain scrap tires pose an ideal breeding ground for mosquitoes, which can breed 100 times faster in the warm, stagnant water standing in scrap tire casings. Severe illnesses, including West Nile Virus, have been attributed to disease-carrying mosquitoes. The potential for tire fires is also reduced by removing illegally dumped tires. Tire fires can result in the contamination of air, surface water, ground water, and soil. In addition, neighborhoods have been evacuated and property damage has been significant due to tire dump sites that caught fire. Illegal tire dumping can also impact drainage of runoff, making areas more susceptible to flooding when wastes block waterways. Open burning at tire dump sites can cause forest fires and erosion as fires burn away trees and undergrowth. Tire dumping has a negative impact on trees and wildlife, and runoff from tire dumpsites may contain chemicals that can contaminate wells and surface water used for drinking.

c. Minimum Expenditure

The Respondent shall contribute at least the SEP Offset Amount to the Third-Party Administrator and comply with all other provisions of this SEP.

2. Performance Schedule

Within 30 days after the effective date of this Agreed Order, the Respondent must contribute the SEP Offset Amount to the Third-Party Administrator. The Respondent shall make the check payable to **Texas Association of RC&D SEP** and shall mail the contribution with a copy of the Agreed Order to:

The Premcor Refining Group Inc.
Agreed Order - Attachment A

Texas Association of RC&D Areas, Inc.
Attn.: Jerry Pearce, Executive Director
P.O. Box 2533
Victoria, Texas 77902

3. Records and Reporting

Concurrent with the payment of the SEP Offset Amount, the Respondent shall provide the Enforcement SEP Coordinator with a copy of the check and transmittal letter indicating full payment of the SEP Offset Amount to the Third-Party Administrator. The Respondent shall mail a copy of the check and transmittal letter to:

Texas Commission on Environmental Quality
Enforcement Division
Attention: SEP Coordinator, MC 219
P.O. Box 13087
Austin, Texas 78711-3087

4. Failure to Fully Perform

If the Respondent does not perform its obligations under this Attachment A, including full expenditure of the SEP Offset Amount, as described in Sections 2 and 3 above, the ED may require immediate payment of all or part of the SEP Offset Amount.

In the event the ED determines that the Respondent failed to fully implement and complete the Project, the Respondent shall remit payment for all or a portion of the SEP Offset Amount, as determined by the ED, and as set forth in the attached Agreed Order. After receiving notice of failure to complete the SEP, the Respondent shall include the docket number of the attached Agreed Order and a note that the enclosed payment is for the reimbursement of a SEP. The Respondent shall make the check payable to "Texas Commission on Environmental Quality" and shall mail it to:

Texas Commission on Environmental Quality
Litigation Division
Attention: SEP Coordinator, MC 175
P.O. Box 13087
Austin, Texas 78711-3087

5. Publicity

Any public statements concerning this SEP and/or project, made by or on behalf of the Respondent must include a clear statement that **the project was performed as part of the settlement of an enforcement action brought by the TCEQ**. Such statements include advertising, public relations, and press releases.

6. Clean Texas Program

The Respondent shall not include this SEP in any application made to TCEQ under the "Clean Texas" (or any successor) program(s). Similarly, the Respondent may not seek recognition for this contribution in any other state or federal regulatory program.

7. Other SEPs by TCEQ or Other Agencies

The SEP Offset Amount identified in this Attachment A and in the attached Agreed Order has not been, and shall not be, included as a SEP for the Respondent under any other Agreed Order negotiated with the TCEQ or any other agency of the state or federal government.



Penalty Calculation Worksheet (PCW)

Policy Revision 4 (April 2014)

PCW Revision March 26, 2014

TCEQ

DATES	Assigned	16-Jun-2014	Screening	25-Jun-2014	EPA Due	8-Mar-2015
	PCW	25-Jun-2014				

RESPONDENT/FACILITY INFORMATION

Respondent	The Premcor Refining Group Inc.		
Reg. Ent. Ref. No.	RN102584026		
Facility/Site Region	10-Beaumont	Major/Minor Source	Major

CASE INFORMATION

Enf./Case ID No.	48895	No. of Violations	1
Docket No.	2014-0903-AIR-E	Order Type	Findings
Media Program(s)	Air	Government/Non-Profit	No
Multi-Media		Enf. Coordinator	Rajesh Acharya
		EC's Team	Enforcement Team 4
Admin. Penalty \$ Limit Minimum		\$0	Maximum
			\$25,000

Penalty Calculation Section

TOTAL BASE PENALTY (Sum of violation base penalties)	Subtotal 1	\$25,000
---	-------------------	----------

ADJUSTMENTS (+/-) TO SUBTOTAL 1

Subtotals 2-7 are obtained by multiplying the Total Base Penalty (Subtotal 1) by the indicated percentage.

Compliance History	100.0% Enhancement	Subtotals 2, 3, & 7	\$25,000
---------------------------	--------------------	--------------------------------	----------

Notes: Enhancement for five NOV's with same/similar violations, six orders with a denial of liability, and one court order with a denial of liability. Reduction for seven Notices of Audit, two Disclosures of Violations, and one Environmental Management System.

Culpability	No	0.0% Enhancement	Subtotal 4	\$0
--------------------	----	------------------	-------------------	-----

Notes: The Respondent does not meet the culpability criteria.

Good Faith Effort to Comply Total Adjustments	Subtotal 5	\$0
--	-------------------	-----

Economic Benefit	0.0% Enhancement*	Subtotal 6	\$0
-------------------------	-------------------	-------------------	-----

Total EB Amounts: \$250
Approx. Cost of Compliance: \$5,000
*Capped at the Total EB \$ Amount

SUM OF SUBTOTALS 1-7	Final Subtotal	\$50,000
-----------------------------	-----------------------	----------

OTHER FACTORS AS JUSTICE MAY REQUIRE	0.0%	Adjustment	\$0
---	------	-------------------	-----

Reduces or enhances the Final Subtotal by the indicated percentage.

Notes:

Final Penalty Amount	\$50,000
-----------------------------	----------

STATUTORY LIMIT ADJUSTMENT	Final Assessed Penalty	\$25,000
-----------------------------------	-------------------------------	----------

DEFERRAL	0.0% Reduction	Adjustment	\$0
-----------------	----------------	-------------------	-----

Reduces the Final Assessed Penalty by the indicated percentage. (Enter number only; e.g. 20 for 20% reduction.)

Notes:

No deferral is recommended for Findings Orders.

PAYABLE PENALTY	\$25,000
------------------------	----------

Screening Date 25-Jun-2014

Docket No. 2014-0903-AIR-E

PCW

Respondent The Premcor Refining Group Inc.

Policy Revision 4 (April 2014)

Case ID No. 48895

PCW Revision March 26, 2014

Reg. Ent. Reference No. RN102584026

Media [Statute] Air

Enf. Coordinator Rajesh Acharya

Compliance History Worksheet

>> Compliance History Site Enhancement (Subtotal 2)

Component	Number of...	Enter Number Here	Adjust.
NOVs	Written notices of violation ("NOVs") with same or similar violations as those in the current enforcement action (<i>number of NOVs meeting criteria</i>)	5	25%
	Other written NOVs	0	0%
Orders	Any agreed final enforcement orders containing a denial of liability (<i>number of orders meeting criteria</i>)	6	120%
	Any adjudicated final enforcement orders, agreed final enforcement orders without a denial of liability, or default orders of this state or the federal government, or any final prohibitory emergency orders issued by the commission	0	0%
Judgments and Consent Decrees	Any non-adjudicated final court judgments or consent decrees containing a denial of liability of this state or the federal government (<i>number of judgments or consent decrees meeting criteria</i>)	1	30%
	Any adjudicated final court judgments and default judgments, or non-adjudicated final court judgments or consent decrees without a denial of liability, of this state or the federal government	0	0%
Convictions	Any criminal convictions of this state or the federal government (<i>number of counts</i>)	0	0%
Emissions	Chronic excessive emissions events (<i>number of events</i>)	0	0%
Audits	Letters notifying the executive director of an intended audit conducted under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (<i>number of audits for which notices were submitted</i>)	7	-7%
	Disclosures of violations under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (<i>number of audits for which violations were disclosed</i>)	2	-4%
Please Enter Yes or No			
Other	Environmental management systems in place for one year or more	Yes	-10%
	Voluntary on-site compliance assessments conducted by the executive director under a special assistance program	No	0%
	Participation in a voluntary pollution reduction program	No	0%
	Early compliance with, or offer of a product that meets future state or federal government environmental requirements	No	0%

Adjustment Percentage (Subtotal 2) 154%

>> Repeat Violator (Subtotal 3)

No

Adjustment Percentage (Subtotal 3) 0%

>> Compliance History Person Classification (Subtotal 7)

Satisfactory Performer

Adjustment Percentage (Subtotal 7) 0%

>> Compliance History Summary

Compliance History Notes

Enhancement for five NOVs with same/similar violations, six orders with a denial of liability, and one court order with a denial of liability. Reduction for seven Notices of Audit, two Disclosures of Violations, and one Environmental Management System.

Total Compliance History Adjustment Percentage (Subtotals 2, 3, & 7) 154%

>> Final Compliance History Adjustment

Final Adjustment Percentage *capped at 100% 100%

Screening Date 25-Jun-2014
Respondent The Premcor Refining Group Inc.
Case ID No. 48895
Reg. Ent. Reference No. RN102584026
Media [Statute] Air
Enf. Coordinator Rajesh Acharya
Violation Number 1

Docket No. 2014-0903-AIR-E

PCW

Policy Revision 4 (April 2014)
PCW Revision March 26, 2014

Rule Cite(s)

30 Tex. Admin. Code §§ 101.20(3), 116.115(b)(2)(F), 116.115(c), and 122.143(4), Tex. Health & Safety Code § 382.085(b), Federal Operating Permit No. 01498, Special Terms and Conditions No. 18, and New Source Review Permit Nos. 6825A, PSDTX49, and N65, Special Conditions No. 1

Violation Description

Failed to prevent unauthorized emissions. Specifically, the Respondent released 110,224.70 pounds ("lbs") of sulfur dioxide, 3,270.70 lbs of volatile organic compounds, 28.80 lbs of particulate matter, 2,654.50 lbs of carbon monoxide, 367.60 lbs of nitrogen oxides, 1,195.90 lbs of hydrogen sulfide, and 109.70 lbs of ammonia during an emissions event (Incident No. 193520) that began on January 27, 2014 and lasted 5 hours and 20 minutes. These emissions were released from Emissions Point Numbers E-23-FLARE and E-26-FLARE. The event occurred when the Wet Gas Compressor K-6300 2nd Stage Anti-surge Valve tripped due to instrumentation failure. The trip was caused by an erroneous signal from Flow Transmitter ("FT") 30-FT-2806 which was due to a partial blockage of the FT manifold (high side only). The source of the blockage was suspected to be foreign debris and/or hydrate formation due to lack of adequate insulation aggravated by unusually cold winter weather. Since this event could have been avoided by better operational practices, the Respondent is precluded from asserting an affirmative defense under 30 Tex. Admin. Code § 101.222.

Base Penalty

\$25,000

>> Environmental, Property and Human Health Matrix

OR

Release	Major	Moderate	Minor
Actual	x		
Potential			

Percent 100.0%

>> Programmatic Matrix

Falsification	Major	Moderate	Minor

Percent 0.0%

Matrix Notes

Human health or the environment has been exposed to pollutants which exceed levels that are protective of human health or environmental receptors as a result of the violation.

Adjustment \$0

\$25,000

Violation Events

Number of Violation Events 1

1 Number of violation days

mark only one with an x

daily	x
weekly	
monthly	
quarterly	
semiannual	
annual	
single event	

Violation Base Penalty \$25,000

One daily event is recommended.

Good Faith Efforts to Comply

0.0% Reduction

\$0

	Before NOV	NOV to EDPRP/Settlement Offer
Extraordinary		
Ordinary		
N/A	x	(mark with x)

Notes

The Respondent does not meet the good faith criteria for this violation.

Violation Subtotal \$25,000

Economic Benefit (EB) for this violation

Statutory Limit Test

Estimated EB Amount \$250

Violation Final Penalty Total \$50,000

This violation Final Assessed Penalty (adjusted for limits) \$25,000

Economic Benefit Worksheet

Respondent The Premcor Refining Group Inc.

Case ID No. 48895

Reg. Ent. Reference No. RN102584026

Media Air

Violation No. 1

Percent Interest 5.0
Years of Depreciation 15

Item Cost **Date Required** **Final Date** **Yrs** **Interest Saved** **Onetime Costs** **EB Amount**
Item Description No commas or \$

Delayed Costs

Equipment				0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/Construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)	\$5,000	27-Jan-2014	27-Jan-2015	1.00	\$250	n/a	\$250

Notes for DELAYED costs

Estimated cost to implement measures and procedures designed to prevent the recurrence of emissions events due to the same cause as Incident No. 193520. Date Required is the date the emissions event began. Final Date is the estimated compliance date.

Avoided Costs

ANNUALIZE [1] avoided costs before entering item (except for one-time avoided costs)

Disposal			0.00	\$0	\$0	\$0
Personnel			0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling			0.00	\$0	\$0	\$0
Supplies/Equipment			0.00	\$0	\$0	\$0
Financial Assurance [2]			0.00	\$0	\$0	\$0
ONE-TIME avoided costs [3]			0.00	\$0	\$0	\$0
Other (as needed)			0.00	\$0	\$0	\$0

Notes for AVOIDED costs

Approx. Cost of Compliance

\$5,000

TOTAL

\$250



TCEQ Compliance History Report

PUBLISHED Compliance History Report for CN601420748, RN102584026, Rating Year 2013 which includes Compliance History (CH) components from September 1, 2008, through August 31, 2013.

Customer, Respondent, or Owner/Operator:	CN601420748, The Premcor Refining Group Inc.	Classification: SATISFACTORY	Rating: 41.48
Regulated Entity:	RN102584026, VALERO PORT ARTHUR REFINERY	Classification: SATISFACTORY	Rating: 55.00
Complexity Points:	30	Repeat Violator:	NO
CH Group:	02 - Oil and Petroleum Refineries		
Location:	1801 SOUTH GULFWAY DR PORT ARTHUR, TX 77640-4416, JEFFERSON COUNTY		
TCEQ Region:	REGION 10 - BEAUMONT		

ID Number(s):

AIR OPERATING PERMITS PERMIT 3423
AIR OPERATING PERMITS PERMIT 1498
AIR OPERATING PERMITS PERMIT 2228
INDUSTRIAL AND HAZARDOUS WASTE EPA ID TXD008090409
INDUSTRIAL AND HAZARDOUS WASTE PERMIT 50350
AIR NEW SOURCE PERMITS PERMIT 6825A
AIR NEW SOURCE PERMITS REGISTRATION 12553A
AIR NEW SOURCE PERMITS REGISTRATION 13698A
AIR NEW SOURCE PERMITS ACCOUNT NUMBER JE0042B
AIR NEW SOURCE PERMITS EPA PERMIT N65
AIR NEW SOURCE PERMITS REGISTRATION 84929
AIR NEW SOURCE PERMITS PERMIT 86757
AIR NEW SOURCE PERMITS REGISTRATION 91727
AIR NEW SOURCE PERMITS REGISTRATION 94365
AIR NEW SOURCE PERMITS REGISTRATION 103875
AIR NEW SOURCE PERMITS REGISTRATION 118687
AIR NEW SOURCE PERMITS REGISTRATION 114829
AIR EMISSIONS INVENTORY ACCOUNT NUMBER JE0042B

AIR OPERATING PERMITS ACCOUNT NUMBER JE0042B
AIR OPERATING PERMITS PERMIT 2227
AIR OPERATING PERMITS PERMIT 2229
INDUSTRIAL AND HAZARDOUS WASTE SOLID WASTE REGISTRATION # (SWR) 30004
AIR NEW SOURCE PERMITS REGISTRATION 17038
AIR NEW SOURCE PERMITS REGISTRATION 12454A
AIR NEW SOURCE PERMITS REGISTRATION 13635A
AIR NEW SOURCE PERMITS REGISTRATION 28778
AIR NEW SOURCE PERMITS AFS NUM 4824500004
AIR NEW SOURCE PERMITS PERMIT 80812
AIR NEW SOURCE PERMITS REGISTRATION 84905
AIR NEW SOURCE PERMITS REGISTRATION 87917
AIR NEW SOURCE PERMITS REGISTRATION 91911
AIR NEW SOURCE PERMITS EPA PERMIT PSDTX49M1
AIR NEW SOURCE PERMITS REGISTRATION 112591
AIR NEW SOURCE PERMITS REGISTRATION 109221
IHW CORRECTIVE ACTION SOLID WASTE REGISTRATION # (SWR) 30004
POLLUTION PREVENTION PLANNING ID NUMBER P00987

Compliance History Period: September 01, 2008 to August 31, 2013 **Rating Year:** 2013 **Rating Date:** 09/01/2013
Date Compliance History Report Prepared: June 25, 2014
Agency Decision Requiring Compliance History: Enforcement
Component Period Selected: June 25, 2009 to June 25, 2014
TCEQ Staff Member to Contact for Additional Information Regarding This Compliance History.

Name: Rajesh Acharya

Phone: (512) 239-0577

Site and Owner/Operator History:

- | | |
|--|-----|
| 1) Has the site been in existence and/or operation for the full five year compliance period? | YES |
| 2) Has there been a (known) change in ownership/operator of the site during the compliance period? | NO |
| 3) If YES for #2, who is the current owner/operator? | N/A |
| 4) If YES for #2, who was/were the prior owner(s)/operator(s)? | N/A |
| 5) If YES , when did the change(s) in owner or operator occur? | N/A |

Components (Multimedia) for the Site Are Listed in Sections A - J

A. Final Orders, court judgments, and consent decrees:

- 1 Effective Date: 08/31/2009 ADMINORDER 2009-0151-AIR-E (1660 Order-Agreed Order With Denial)
Classification: Moderate
Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
 30 TAC Chapter 116, SubChapter G 116.715(a)
 30 TAC Chapter 116, SubChapter G 116.715(c)(7)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THSC Chapter 382 382.085(b)
Rqmt Prov:6825A/PSD-TX-49, SC 5A PERMIT
 O-01498, GENERAL CONDITIONS OP
Description: Failed to prevent unauthorized emissions during Incident No. 108928.
Classification: Moderate
Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
 30 TAC Chapter 116, SubChapter G 116.715(a)
 30 TAC Chapter 116, SubChapter G 116.715(c)(7)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THSC Chapter 382 382.085(b)
Rqmt Prov:6825A/PSD-TX-49, SC 5A PERMIT
 O-01498, GENERAL CONDITIONS OP
Description: Failed to prevent unauthorized emissions during Incident No. 111065.
Classification: Moderate
Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
 30 TAC Chapter 116, SubChapter G 116.715(a)
 30 TAC Chapter 116, SubChapter G 116.715(c)(7)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THSC Chapter 382 382.085(b)
Rqmt Prov:6825A/PSD-TX-49, SC 5A PERMIT
 O-01498, GENERAL CONDITIONS OP
Description: Failed to prevent unauthorized emissions during Incident No. 113023.
- 2 Effective Date: 09/23/2009 COURTORDER (Final Judgement-Agreed Order With Denial)
Classification: Moderate
Citation: 5C THSC Chapter 382 382.085
Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation conducted at the Port Arthur, Texas refinery on or about April 4, 2003, referred to as investigation no. 28570. The investigation describes the violations in narrative form and identifies the violations by tracking numbers 44442, 44448, 44454, 44459, 44462, 44472, 44477, 44496, 44498, 44512, 44517, 44519, 44532, 44535, 44550, 44557
Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(G)
 5C THC Chapter 382, SubChapter A 382.085(b)
Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(G)
 5C THC Chapter 382, SubChapter A 382.085(b)
Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(G)
 5C THC Chapter 382, SubChapter A 382.085(b)
Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(G)
 5C THC Chapter 382, SubChapter A 382.085(b)
Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(G)
 5C THC Chapter 382, SubChapter A 382.085(b)
Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(G)
 5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Flexible Permit 6825A, SC 5B PERMIT
PSD-TX-49, SC 5B PERMIT

Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.110(a)(4)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Standard Exemption No. 88 PA

Description: Failure to satisfy the condition of a standard exemption.
Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.110(a)(4)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Standard Exemption 88 PA

Description: Failure to meet the conditions of a standard exemption.
Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(G)
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Flexible Permit 6825A, SC 5B PERMIT
PSD-TX-49, SC 5B PERMIT

Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.110(a)(4)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Standard Exemption 88 PA

Description: Failure to meet the conditions of a standard exemption.
Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Flexible Permit 6825A, SC 5B PERMIT
PSD-TX-49, SC 5B PERMIT

Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.110(a)(4)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Standard Exemption 88 PA

Description: Failure to meet the conditions of a standard exemption.
Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(G)

30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:5215A, SC1 PERMIT

Description: Failure to maintain emission rate below allowable limit.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Flexible Permit 6825A, SC 5B PERMIT

PSD-TX-49, SC 5B PERMIT

Description: Failure to maintain emission rate below allowable limit.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Flexible Permit 6825A, SC19 PERMIT

PSD-TX-49, SC 19 PERMIT

Description: Failure to comply with requirements of a permit.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Flexible Permit, 6825A SC 5B PERMIT

PSD-TX-49, SC5B PERMIT

Description: Failure to maintain emission rate below allowable limit.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Flexible permit 6825A, SC 5B PERMIT

PSD-TX-49, SC 5B PERMIT

Description: Failure to maintain emission rate below allowable limit.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Flexible Permit 6825A, SC 5B PERMIT

PSD-TX-49, SC 5B PERMIT

Description: Failure to maintain emission rate below allowable limit.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.110(a)(4)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Standard Exemption No. 88 PA

Description: Failure to satisfy the condition of a standard exemption.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.110(a)(4)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Standard Exemption No. 88 PA

Description: Failure to meet the conditions of a standard exemption.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Flexible Permit 6825A, SC 5B PERMIT
PSD-TX-49, SC 5B PERMIT

Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate

Citation:
30 TAC Chapter 101, SubChapter A 101.20(3)
Classification: Moderate
30 TAC Chapter 116, SubChapter B 116.110(a)(4)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Flexible Permit 6825A, SC 5B PERMIT
PSD-TX-49, SC 5 PERMIT
Standard Exemption No. 88 PA

Description: Failure to maintain emission rate below allowable limit and meet the conditions of a standard exemption.
Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Flexible Permit 6825A, SC 5B PERMIT
PSD-TX-49, SC 5B PERMIT

Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate

Citation: 5C THC Chapter 382, SubChapter A 382.085(a)

Description: Failure to prevent unauthorized emissions.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(G)
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to maintain emission rate below allowable limit.
Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.6(a)(1)(B)
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failed to report an upset within 24 hours of the event.
Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(2)(H)
30 TAC Chapter 101, SubChapter F 101.201(b)(4)
30 TAC Chapter 101, SubChapter F 101.201(b)(8)
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to report all information required for emissions event.
Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(2)(G)
30 TAC Chapter 101, SubChapter F 101.201(a)(2)(H)
30 TAC Chapter 101, SubChapter F 101.201(b)(4)
30 TAC Chapter 101, SubChapter F 101.201(b)(8)
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to report all information required for emissions event.
Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(2)(H)
30 TAC Chapter 101, SubChapter F 101.201(b)(4)
30 TAC Chapter 101, SubChapter F 101.201(b)(8)

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(2)(H)
30 TAC Chapter 101, SubChapter F 101.201(b)(4)
30 TAC Chapter 101, SubChapter F 101.201(b)(8)
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to report all information required for an emissions event.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(b)(4)
30 TAC Chapter 101, SubChapter F 101.201(b)(8)

Description: Failure to report all information required for an emissions event.

Classification: Moderate

Citation: 5C THSC Chapter 382 382.085

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation conducted at the Port Arthur, Texas refinery on or about August 12, 1998. By an August 31, 1998 letter to the Defendants, The TCEQ listed the violations observed during the investigation. A copy of the August 12, 1998 investigation, without attachments, is attached as Appendix A and incorporated herein for all purposes

Classification: Moderate

Citation: 5C THSC Chapter 382 382.085

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation conducted at the Port Arthur, Texas refinery on or about March 12, 1999. By a March 22, 1999 letter to the Defendants, the TCEQ listed the violations observed during the investigation. A copy of the March 22, 1999, letter to the Defendants is attached as Appendix C and incorporated herein for all purposes.

Classification: Moderate

Citation: 5C THC Chapter 382, SubChapter A 382.085

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation conducted at the Port Arthur, Texas refinery on or about July 17, 1999. The TCEQ describes the violation observed during the investigation in a July 9, 1999, Enforcement Action Referral. A copy of the July 9, 1999, Enforcement Action Referral, without attachments, is attached as Appendix D and incorporated herein for all purposes.

Classification: Moderate

Citation: 5C THSC Chapter 382 382.085

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in investigations conducted at the Port Arthur, Texas refinery on or about June 14, 1999 and August 4, 1999. By June 30, 1999 and August 24, 1999, letters to the Defendants, the TCEQ listed the violations observed during the two investigations. A copy of the June 14, 1999 investigation, without attachments, is attached as Appendix E and incorporated

Classification: Minor

Citation: 5C THSC Chapter 382 382.085

Rqmt Prov:SC39A PERMIT

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation conducted at the Port Arthur, Texas refinery on or about July 20, 2000. By a September 7, 2000, letter to the Defendants, the TCEQ listed the violations observed during the investigation. A copy of the July 20, 2000 investigation, without attachments, is attached as Appendix I and incorporated herein for all purposes . . .

Classification: Moderate

Citation: 5C THSC Chapter 382 382.085

Rqmt Prov:NA PERMIT

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in investigations conducted at the Port Arthur, Texas refinery on or about November 3, 2000, and March 26, 2001. By April 21, 2001 letter to the Defendants, the TCEQ listed the violations observed during the investigation. A copy of the November 3, 2000 investigation, without attachments, is attached as Appendix K and incorporated herein for all purposes

Classification: Moderate

Citation: 5C THSC Chapter 382 382.085

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation conducted at the Port Arthur, Texas refinery on or about April 3, 2001. By April 24, 2001 letter to the Defendants, the TCEQ listed the violation observed during the investigation. A copy of the April 3, 2001 investigation, without attachments, is attached as Appendix N and incorporated herein for all purposes

Classification: Moderate

Citation: 5C THSC Chapter 382 382.085

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation conducted at the Port Arthur, Texas refinery on or about November 12, 2003, referred to as investigation no. 258663. The investigation describes the violation in narrative form and identifies the violation by tracking number 150854 in the investigation. A copy of investigation no. 258663, without attachments

Classification: Minor

Citation: 5C THSC Chapter 382 382.085

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation conducted at the Port Arthur, Texas refinery on or about April 20, 2004 referred to as investigation no. 270296. The investigation describes the violations in narrative form and identifies the violations by tracking numbers 161061 and 161062 in the investigation. A copy of investigation no. 270296, without attachments

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)

30 TAC Chapter 116, SubChapter G 116.715(c)(7)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Permit 6825A Special Condion 5B PA

PSD-TX-49 Special Condion 5B PA

Description: Failure to prevent unauthorized emissions release at the facility.

Classification: Minor

Citation: 5C THSC Chapter 382 382.085

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation conducted at the Port Arthur, Texas refinery on or about January 20, 2005, referred to as investigation no. 276009. The investigation describes the violations in narrative form and identifies the violations by tracking numbers 188937, 188938, 188940, 188941, 188942, 188943, 188944, 188945, 188946, 188947, 188948, 188949, 188950, and

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 111, SubChapter A 111.111(a)(1)(B)

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:6825A/PSD-TX-49, SC 25A PERMIT

Description: Failure to prevent visible emissions at the Atmospheric Vacuum Unit (AVU)-146 H-101 Heater.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:6825A/PSD-TX-49, SC 5A PERMIT

Description: Failure to maintain an emission rate below the emission cap's hourly contribution limit.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(2)(G)

30 TAC Chapter 101, SubChapter F 101.201(b)(7)

30 TAC Chapter 101, SubChapter F 101.201(b)(8)

5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to properly notify the regional office of a reportable emissions event, which began on April 14, 2004 (STEERS Incident 37961).

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(2)(H)

30 TAC Chapter 101, SubChapter F 101.201(b)(8)

5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to properly identify authorized emissions limits for an emissions event, which began on April 14, 2004 (STEERS Incident 37961).

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:6825A/PSD-TX-49, SC 5A PERMIT

Description: Failure to maintain an emission rate below the emission cap limits.

Failure to maintain an emission rate below the emission cap limits.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(2)(D)

30 TAC Chapter 101, SubChapter F 101.201(b)(4)

30 TAC Chapter 101, SubChapter F 101.201(b)(7)

30 TAC Chapter 101, SubChapter F 101.201(b)(8)

5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to properly notify the regional office of a reportable emissions event, which began on April 14, 2004 (STEERS Incident 37962).

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(2)(H)

30 TAC Chapter 101, SubChapter F 101.201(b)(8)

5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to properly identify authorized emissions limits for an emissions event, which began on April 14, 2004 (STEERS Incident 37962).

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:6825A/PSD-TX-49, SC 5A PERMIT

Description: Failure to maintain an emission rate below the emission cap limits.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(b)(7)

30 TAC Chapter 101, SubChapter F 101.201(b)(8)

5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to properly notify the regional office of a reportable emissions event, which began on April 14, 2004 (STEERS Incident 38022).

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(2)(H)

30 TAC Chapter 101, SubChapter F 101.201(b)(8)

5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to properly identify authorized emissions limits for an emissions event, which began on April 14, 2004 (STEERS Incident 38022).

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:6825A/PSD-TX-49, SC 5A PERMIT

Description: Failure to maintain an emission rate below the emission cap limits.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(b)(7)

30 TAC Chapter 101, SubChapter F 101.201(b)(8)

5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to properly notify the regional office of a reportable emissions event, which began on April 14, 2004 (STEERS Incident 38026).

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:6825A/PSD-TX-49, SC 5A PERMIT

Description: Failure to maintain an emission rate below the emission cap's hourly contribution limit.

Classification: Moderate

Citation: 5C THSC Chapter 382 382.085

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation conducted at the Port Arthur, Texas refinery on or about January 24, 2005, referred to as investigation no. 346253. The investigation describes the violations in narrative form and identifies the violations by tracking numbers 190534, 190543, 190551, and 190558 in the investigation. A copy of investigation no. 346253, without attachments . . .

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

30 TAC Chapter 116, SubChapter G 116.715(c)(7)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:Permit 6825A, PSD-TX-49, SC 5A PA

Description: Failure to prevent unauthorized emissions from the Atmospheric Vacuum Unit (AVU) 146 during incident No. 32824.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)(B)

5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to report an emission event (Incident No. 33539) within 24 hours

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: Permit 6825A, PSD-TX-49, SC 17C PA
Permit 6825A, PSD-TX-49, SC 5A PA

Description: Failure to prevent unauthorized emissions from the Scot 1 Incinerator during incident No. 33539 and failure to continuously monitor from hydrocarbon layer thickness by electronic gauge.
Classification: Moderate

Citation: 5C THSC Chapter 382 382.085

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation conducted at the Port Arthur, Texas refinery on or about April 8, 2005, referred to as investigation no. 348169. The investigation describes the violations in narrative form and identifies the violation by tracking numbers 208879 in the investigation. A copy of investigation no. 348169, without attachments, is attached as Appendix U

Classification: Moderate

Citation: 5C THSC Chapter 382 382.085

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation the Port Arthur, Texas refinery on or about June 30, 2005, referred to as investigation no. 396901. The investigation describes the violations in narrative form and identifies the violations by tracking numbers 210570 and 210577 in the investigation. A copy of investigation no. 396901, without attachments, is attached as Appendix V

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: 6825A/PSD-TX-49 PERMIT

Description: Failure to prevent unauthorized emissions during Incident Nos. 40540, 40543, 51468, and 53830.

Classification: Moderate

Citation: 5C THSC Chapter 382 382.085

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation the Port Arthur, Texas refinery on or about July 27, 2005, referred to as investigation no. 402102. The investigation describes the violations in narrative form and identifies the violations by tracking numbers 212393 and 212460 in the investigation. A copy of investigation no. 402102, without attachments, is attached as Appendix X and incorpo

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: 6825A/PSD-TX-49 PERMIT

Description: Failure to prevent unauthorized emissions during Incident Nos. 51075, 51078, 51081, 51084, and 51087.

Classification: Minor

Citation: 5C THSC Chapter 382 382.085

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation the Port Arthur, Texas refinery on or about July 26, 2005, referred to as investigation no. 403310. The investigation describes the violations in narrative form and identifies the violations by tracking numbers 213083, 213088, and 213090 in the investigation. A copy of investigation no. 403310, without attachments

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)(A)
30 TAC Chapter 101, SubChapter F 101.201(a)(1)(B)
30 TAC Chapter 101, SubChapter F 101.211(a)
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to submit an initial notification for an emissions event.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 116, SubChapter G 116.715(c)(7)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: 6825A/PSD-TX-49, SC 5A PERMIT

Description: Failure to maintain an emission rate below the allowable emission limit.

Classification: Moderate

Citation: 5C THSC Chapter 382 382.085

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation the Port Arthur, Texas refinery on or about August 8, 2005, referred to as investigation no. 337449. The investigation describes the violations in narrative form and identifies the violations by tracking numbers 214475 and 214478 in the investigation. A copy of investigation no. 337449, without attachments, is attached as Appendix Y

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter G 116.715(c)(9)

5C THSC Chapter 382, SubChapter A 382.085(b)

Description: Failure to maintain the CO 9 Boiler bypass valve to prevent unauthorized emissions during normal operation

from April 2004 to the end of February 2005. B13

Classification: Moderate

Citation: 5C THSC Chapter 382 382.085

Description: Defendants violated Section 382.085 of the TCAA, and regulations promulgated and permits issued to implement the TCAA, as documented in an investigation the Port Arthur, Texas refinery on or about August 29, 2005, referred to as investigation no. 418593. The investigation describes the violations in narrative form and identifies the violations by tracking number 218082 in the investigation. A copy of investigation no. 418593, without attachments, is attached as Appendix Z and

3 Effective Date: 03/20/2010 ADMINORDER 2009-0511-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

30 TAC Chapter 116, SubChapter G 116.715(c)(7)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:6825A/PSD-TX-49 PERMIT

O-01498 OP

Description: Failure to maintain an emission rate below the allowable emission limits.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

30 TAC Chapter 116, SubChapter G 116.715(c)(7)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:6825A/PSD-TX-49, SC 5A PERMIT

O-01498, GENERAL CONDITIONS OP

Description: Failure to maintain an emission rate below the allowable emission limits.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

30 TAC Chapter 116, SubChapter G 116.715(c)(7)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:6825A/PSD-TX-49, SC 5A PERMIT

O-01498, GENERAL CONDITIONS OP

Description: Failure to maintain an emission rate below the allowable emission limits.

4 Effective Date: 11/18/2011 ADMINORDER 2010-0909-MLM-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

30 TAC Chapter 116, SubChapter G 116.715(c)(7)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:FOP 01498, GTC OP

FOP 01498, STC 18 OP

NSR Permit 6825A, SC 1 PERMIT

Description: Failed to prevent unauthorized emissions at the Port Arthur Refinery.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)(A)

30 TAC Chapter 101, SubChapter F 101.201(a)(1)(B)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)

Rqmt Prov:FOP 01498 OP

FOP 01498, GTC OP

Description: Failed to submit an initial report within 24 hours for Incident No. 134571 at the Port Arthur Refinery. Specifically, the incident occurred on January 15, 2010 at 5:51 p.m., but was not reported until January 18, 2010 at 9:20 a.m.

5 Effective Date: 02/18/2012 ADMINORDER 2011-1355-AIR-E (1660 Order-Agreed Order With Denial)
Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)

Rqmt Prov:FOP 01498 STC 18 OP

FOP 01498, General Terms and Conditions OP

NSR Permit 6825A, SC 1 PERMIT

Description: Failed to prevent unauthorized emissions.

Classification: Moderate

Citation: 30 TAC Chapter 106, SubChapter A 106.4(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)

Rqmt Prov:FOP 02228 OP

FOP 02228, STC 14 OP

Description: Failed to prevent unauthorized emissions.

Classification: Moderate

Citation: 30 TAC Chapter 106, SubChapter A 106.4(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)

Rqmt Prov:FOP 02228, General Terms and Conditions OP

FOP 02228, STC 14 OP

Description: Failed to prevent unauthorized emissions.

See addendum for information regarding federal actions.

B. Criminal convictions:

N/A

C. Chronic excessive emissions events:

N/A

D. The approval dates of investigations (CCEDS Inv. Track. No.):

Item 1	June 29, 2009	(760309)
Item 2	August 26, 2009	(763057)
Item 3	August 28, 2009	(761367)
Item 4	August 31, 2009	(762200)
Item 5	October 07, 2009	(775036)
Item 6	October 13, 2009	(766946)
Item 7	October 14, 2009	(767494)
Item 8	November 06, 2009	(764488)
Item 9	December 09, 2009	(784945)
Item 10	December 11, 2009	(783903)
Item 11	December 21, 2009	(781035)
Item 12	December 23, 2009	(785403)
Item 13	January 29, 2010	(786198)
Item 14	February 01, 2010	(788081)
Item 15	March 19, 2010	(795261)
Item 16	May 06, 2010	(800545)
Item 17	May 24, 2010	(801617)
Item 18	June 01, 2010	(788840)

Item 19	June 02, 2010	(803054)
Item 20	June 07, 2010	(825637)
Item 21	June 11, 2010	(824255)
Item 22	August 02, 2010	(842714)
Item 23	November 15, 2010	(871779)
Item 24	November 30, 2010	(872652)
Item 25	April 15, 2011	(906545)
Item 26	October 25, 2011	(956400)
Item 27	October 29, 2011	(956377)
Item 28	November 02, 2011	(951193)
Item 29	November 29, 2011	(963859)

Item 30	January 17, 2012	(976419)
Item 31	February 17, 2012	(983674)
Item 32	February 21, 2012	(987303)
Item 33	March 16, 2012	(994426)
Item 34	March 23, 2012	(988369)
Item 35	April 30, 2012	(988371)
Item 36	May 17, 2012	(995645)
Item 37	August 07, 2012	(1019646)
Item 38	August 14, 2012	(1023815)
Item 39	August 28, 2012	(1023318)
Item 40	September 11, 2012	(1023427)
Item 41	October 11, 2012	(1036849)
Item 42	October 13, 2012	(1028000)
Item 43	October 15, 2012	(1036124)
Item 44	November 20, 2012	(1042742)
Item 45	February 20, 2013	(1051546)
Item 46	April 30, 2013	(1086243)
Item 47	August 08, 2013	(1109778)
Item 48	August 17, 2013	(1113514)
Item 49	August 26, 2013	(1113154)
Item 50	August 27, 2013	(1115289)
Item 51	October 30, 2013	(1123618)
Item 52	February 27, 2014	(1140405)
Item 53	February 28, 2014	(1152033)
Item 54	April 21, 2014	(1163529)
Item 55	May 08, 2014	(1165599)
Item 56	May 16, 2014	(1164072)
Item 57	May 20, 2014	(1166837)
Item 58	May 27, 2014	(1163802)
Item 59	June 04, 2014	(1171088)

E. Written notices of violations (NOV) (CCEDS Inv. Track. No.):

A notice of violation represents a written allegation of a violation of a specific regulatory requirement from the commission to a regulated entity. A notice of violation is not a final enforcement action, nor proof that a violation has actually occurred.

1	Date:	08/29/2013	(1104962)	
	Self Report?	NO		Classification: Moderate
	Citation:	30 TAC Chapter 101, SubChapter A 101.20(3) 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4) 5C THSC Chapter 382 382.085(b) General Terms and Conditions OP Special Condition 18 OP Special Condition 42F PERMIT		
	Description:	Failure to limit Continuous Emission Monitoring System (CEMS) downtime to less than 5% as reported in the Federal Operating Permit (FOP) O-01498 semi-annual deviation reports for the reporting periods of January 1, 2012, through June 30, 2012, and July 1, 2012, through December 31, 2012.		
	Self Report?	NO		Classification: Moderate
	Citation:	30 TAC Chapter 101, SubChapter A 101.20(1) 30 TAC Chapter 101, SubChapter A 101.20(3) 30 TAC Chapter 116, SubChapter B 116.115(c)		

30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(2)
 5C THSC Chapter 382 382.085(b)
 General Terms and Conditions OP
 Special Condition 18 OP
 Special Condition 1A OP
 Special Condition 6B PERMIT

Description: Failure to operate a flare with a flame present at all times and to continuously monitor the pilot flame by thermocouple or infrared monitor as reported in the FOP O-01498 semi-annual deviation reports for the reporting periods of January 1, 2012, through June 30, 2012, and July 1, 2012, through December 31, 2012.

Self Report? NO **Classification:** Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
 30 TAC Chapter 113, SubChapter C 113.340

30 TAC Chapter 115, SubChapter D 115.352(4)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT GGG 60.592(a)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-6(a)(1)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT AA 63.648(a)
 5C THSC Chapter 382 382.085
 General Terms and Conditions OP
 Special Condition 18 OP
 Special Condition 46E PA
 Special Condition 5A PA
 Special Conditions 1A OP

Description: Failure to install a plug, cap, or blind on an open-ended line for the FOP O-01498 as reported in the FOP O-01498 semi-annual deviation report for the reporting period of January 1, 2012, through June 30, 2012, and July 1, 2012, through December 31, 2012.

Self Report? NO **Classification:** Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
 30 TAC Chapter 101, SubChapter A 101.20(3)
 30 TAC Chapter 113, SubChapter C 113.100
 30 TAC Chapter 113, SubChapter C 113.340
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(3)(ii)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.11(b)(6)(ii)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT AA 63.648(a)
 5C THSC Chapter 382 382.085(b)
 General Terms and Conditions OP
 Special Condition 18 OP
 Special Condition 1A OP
 Special Condition 6A PERMIT

Description: Failure to maintain the net heating value of the flare gas above 300 British Thermal Units (BTU) per standard cubic feet (SCF) as reported as reported in the FOP O-01498 semi-annual deviation report for the reporting period of January 1, 2012, through June 30, 2012.

Self Report? NO **Classification:** Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THSC Chapter 382 382.085(b)
 General Terms and Conditions OP
 Special Condition 18 OP
 Special Condition 25C PERMIT

Description: Failure to limit the refinery fuel gas to no more than 10 grains total sulfur per dry standard cubic feet (dscf) or 160 ppmv on a 1-hour rolling average as reported in the FOP O-01498 semi-annual deviation reports for the reporting periods of January 1, 2012, through June 30, 2012, and July 1, 2012, through December 31, 2012.

Self Report? NO **Classification:** Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 General Terms and Conditions OP
 Special Condition 18 OP
 Special Condition 23B PERMIT

Description: Failure to maintain the tail gas incinerator (TGI) Hydrogen Sulfide (H₂S) concentrations below 5.0 parts per million (ppm) at 3% Oxygen as reported in the FOP O-01498 semi-annual deviation report for the reporting period of January

1, 2012, through June 30, 2012.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
 30 TAC Chapter 101, SubChapter A 101.20(3)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THSC Chapter 382 382.085(b)
 General Terms and Conditions OP
 Special Condition 18 OP
 Special Condition 3A PERMIT

Description: Failure to install, operate, calibrate, and maintain an instrument for continuously monitoring and recording the concentration of NOx emissions into the atmosphere as reported in the FOP O-01498 semi-annual deviation report for the reporting period of July 1, 2012, through December 31, 2012.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
 30 TAC Chapter 101, SubChapter A 101.20(3)
 30 TAC Chapter 113, SubChapter C 113.780
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT J 60.104(a)(2)(i)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT UUU 63.1568(a)(1)
 5C THSC Chapter 382 382.085(b)
 General Terms and Conditions OP
 Special Condition 18 OP
 Special Condition 5B PERMIT

Description: Failure to limit the Sulfur Dioxide (SO2) concentration at or below 250 ppmv at zero percent excess air as reported in the FOP O-01498 semi-annual deviation report for the reporting period of July 1, 2012, through December 31, 2012.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
 30 TAC Chapter 101, SubChapter A 101.20(3)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Part 60, Subpart J 60.103
 5C THSC Chapter 382 382.085(b)
 General Terms and Conditions OP
 Special Condition 18 OP
 Special Condition 3A PERMIT

Description: Failure to comply with the Carbon Monoxide (CO) emission standard of 500 ppm per 1-hour as reported in the FOP O-01498 semi-annual deviation report for the reporting period of July 1, 2012, through December 31, 2012.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THSC Chapter 382 382.085(b)
 General Terms and Conditions OP
 Special Condition 18 OP
 Special Condition 24C PERMIT

Description: Failure to maintain the NOx emissions from the Hydrocracker Unit furnace as reported as reported in the FOP O-01498 semi-annual deviation report for the reporting period of July 1, 2012, through December 31, 2012.

2 Date: 11/22/2013 (1124668) CN601420748

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 61, SubChapter C, PT 61, SubPT FF 61.349(a)(2)(i)(C)
 5C THSC Chapter 382 382.085(b)
 General Terms and Condition OP
 Special Condition 14 OP
 Special Condition 1A OP

Description: Failure to maintain the temperature of the Regenerative Thermal Oxidizer (RTO) in the Waste Water Treatment Unit (WWTU) above 1400 F on April 14, 2013, from 1300 hours to 1500 hours.

3 Date: 11/26/2013 (1133465)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.4
 5C THSC Chapter 382 382.085(b)

Description: Failure to prevent nuisance conditions.

Date: 02/14/2014 (1144920)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 113, SubChapter C 113.340
 30 TAC Chapter 115, SubChapter D 115.352(4)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT GGG 60.592(a)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT AA 63.648(a)
 40 CFR Part 60, Subpart VV 60.482-6
 5C THSC Chapter 382 382.085(b)
 General Terms and Conditions OP
 Special Condition 18 OP
 Special Condition 46E PERMIT
 Special Condition 5A PERMIT

Description: Failure to prevent the release of unauthorized emissions to the atmosphere.

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
 30 TAC Chapter 113, SubChapter C 113.340
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-5(a)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT AA 63.648(a)
 5C THSC Chapter 382 382.085(b)
 General Terms and Conditions OP
 Special Condition 18 OP
 Special Condition 5A PERMIT

Description: Failure to equip each sampling system connection with a closed-purged, closed-loop, or closed-vent system.

Date: 04/23/2014 (1159082)

CN601420748

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THSC Chapter 382 382.085(b)
 General Terms and Conditions OP
 Special Condition 15 OP
 Special Condition 19B PERMIT

Description: Failure to degas liquid sulfur to a H₂S content of 100 parts per million by weight (ppmw) prior to loading into tank trucks as reported in the FOP O-02229 semi-annual deviation report for the reporting periods of January 1, 2013, through June 30, 2013, and July 1, 2013, through December 31, 2013.

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
 30 TAC Chapter 101, SubChapter A 101.20(3)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(2)
 5C THSC Chapter 382 382.085(b)
 General Terms and Conditions OP
 Special Condition 15 OP
 Special Condition 6B PERMIT

Description: Failure to continuously monitor the pilot flame by thermocouple or infrared monitor as reported in the FOP-02229 semi-annual deviation reports for the reporting periods of January 1, 2013, through June 30, 2013.

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
 30 TAC Chapter 113, SubChapter C 113.340
 30 TAC Chapter 115, SubChapter D 115.352(4)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT GGG 60.592(a)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-6(a)(1)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT AA 63.648(a)
 5C THSC Chapter 382 382.085(b)
 General Terms and Conditions OP
 Special Condition 15 OP
 Special Condition 1A OP
 Special Condition 46E PERMIT
 Special Condition 5A PERMIT

Description: Failure to install a plug, cap, or blind on an open-ended line as reported in the FOP O-2229 semi-annual deviation report covering the reporting periods of January 1, 2013, through June 30, 2013, and July 1, 2013, through December

31, 2013.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
General Terms and Conditions OP
Special Condition 15 OP
Special Condition 25C PERMIT

Description: Failure to limit the refinery fuel gas to no more than 10 grains total sulfur per dry standard cubic feet (dscf) or 160 ppmv on a 1-hour rolling average as reported in the FOP O-2229 semi-annual deviation reports for the reporting periods of January 1, 2013, through June 30, 2013, and July 1, 2013, through December 31, 2013.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.352(2)

30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-7(d)(2)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT AA 63.648(a)
5C THSC Chapter 382 382.085(b)
General Terms and Conditions OP
Special Condition 15 OP
Special Condition 46H PERMIT
Special Condition 5A PERMIT

Description: Failure to make the first attempt of repair within five days as reported in the FOP O-02229 semi-annual deviation report for the reporting period of July 1, 2013, through December 31, 2013.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.145(2)(A)
30 TAC Chapter 122, SubChapter B 122.146(1)
5C THSC Chapter 382 382.085(b)
General Terms and Conditions OP

Description: Failure to report a deviation and accurately certify compliance in the FOP O-02229 within the semi-annual deviation reports dated 06/30/2012, 12/31/2012, and 06/30/2013.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.487(c)(2)(vii)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT AA 63.648(a)
5C THSC Chapter 382 382.085(b)
General Terms and Conditions OP
Special Condition 15 OP
Special Condition 5A PERMIT

Description: Failure to identify reasons for delay of repair for components within the 40 CFR 60 Subpart VV semi-annual reports dated June 30, 2012, December 31, 2012, and June 30, 2013

F. Environmental audits:

Notice of Intent Date: 08/21/2009 (775707)

Disclosure Date: 09/08/2010

Viol. Classification: Moderate

Citation: 40 CFR Chapter 122, SubChapter D, PT 122, SubPT C 122.41(a)

Rqmt Prov: PERMIT TPDES Permit # 00309, Pg 20, Cond. 10

Description: Failure to notify the regulatory agency of azure blue dye use. Azure blue dye was being used to treat the tertiary treatment pond, to limit algae growth, without the permit required notifications to the regulatory agency. An initial notification of application was submitted on March 8, 2007 but no further notifications have been made. Dye application typically ends in the Fall, and resumes each Spring. Notifications were not made in 2008 or 2009.

Viol. Classification: Minor

Citation: 40 CFR Chapter 110, SubChapter D, PT 110 112.5(b)

Description: Failed to sign or date the SPCC Plan Form. Figure E-2 of the SPCC Plan contained an "Acknowledgement of SPCC Review" but the form was not signed or dated.

Viol. Classification: Major

Citation: 40 CFR Chapter 122, SubChapter D, PT 122, SubPT B 122.26

Rqmt Prov: PERMIT TPDES Permit # 00309, Condition 9

Description: Failed to implement a SWP3 plan for 7 demolition projects. These projects include the MEK Unit, Pump House #1, Decoker, 9 CO Boiler and Precipitator, 11 Boiler House, 11 Warehouse and the ISOM Unit. Field

visits indicated that all the projects had been completed with the exception of the MEK Unit and Boiler House No. 11 projects which are in progress. An expansion project began in the 3rd Quarter, 2007 but no plan was implemented until November, 2008. A final plan was dated February 6, 2009

Notice of Intent Date: 02/18/2011 (905312)
No DOV Associated

Notice of Intent Date: 06/10/2011 (934095)
No DOV Associated

Notice of Intent Date: 01/19/2012 (988335)
No DOV Associated

Notice of Intent Date: 05/01/2012 (1014133)
No DOV Associated

Notice of Intent Date: 10/17/2012 (1058561)

Disclosure Date: 01/28/2013

Viol. Classification: Minor

Citation: 40 CFR Part 61, Subpart FF 61.356(f)(2)(i)(G)

Description: Failed to be able to locate a certification letter and corresponding design calculation for a carbon adsorption system commissioned on an oil water sump at RSU 1747.

Viol. Classification: Minor

Citation: 40 CFR Chapter 63, SubChapter C, PT 63, SubPT UUU 63.1574(f)

Description: Failed to have an operation, maintenance and monitoring plan for the bypass lines on SRU-54. The lines are HV-1806 for SRU-545 and HV-2682 for SRU-546.

Notice of Intent Date: 07/25/2013 (1105606)
No DOV Associated

G. Type of environmental management systems (EMSs):

1 ENVIRONMENTAL MANAGEMENT SYSTEM NON 30 TAC CH 90 CERTIFIED

H. Voluntary on-site compliance assessment dates:

N/A

I. Participation in a voluntary pollution reduction program:

N/A

J. Early compliance:

N/A

Sites Outside of Texas:

N/A

Addendum to Compliance History Federal Enforcement Actions

Reg Entity Name: THE PREMCOR REFINING GROUP INC

Reg Entity Add: 1801 SOUTH GULFWAY DRIVE

Reg Entity City: PORT ARTHUR

Reg Entity No: RN102584026

Customer Name: The Premcor Refining Group, Inc.

Customer No: CN601420748

EPA Case No: 06-2013-0905

Order Issue Date (yyyymmdd): 20130401

Case Result:

Statute: RCRA

Sect of Statute: 3013

Classification: Minor

Program: Solid Waste Management -

Citation:

Violation Type:

Cite Sect: Subtitle C - Generator ***Cite Part:***

Enforcement Action: Administrative Compliance Order

Customer Name: Valero Energy Corporation

Customer No: CN600127468

EPA Case No: 06-2011-0975

Order Issue Date (yyyymmdd): 20111118

Case Result:

Statute: RCRA

Sect of Statute: 3013

Classification: Minor

Program: RCRA Corrective Action

Citation:

Violation Type:

Cite Sect:

Cite Part:

Enforcement Action: Administrative Compliance Orders

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY



IN THE MATTER OF AN
ENFORCEMENT ACTION
CONCERNING
THE PREMCOR REFINING GROUP
INC.
RN102584026

§ BEFORE THE
§
§ TEXAS COMMISSION ON
§
§
§ ENVIRONMENTAL QUALITY

AGREED ORDER DOCKET NO. 2014-0903-AIR-E

At its _____ agenda, the Texas Commission on Environmental Quality ("the Commission" or "TCEQ") considered this agreement of the parties, resolving an enforcement action regarding The Premcor Refining Group Inc. ("Respondent") under the authority of TEX. HEALTH & SAFETY CODE ch. 382 and TEX. WATER CODE ch. 7. The Executive Director of the TCEQ, through the Enforcement Division, and the Respondent presented this agreement to the Commission.

The Respondent understands that it has certain procedural rights at certain points in the enforcement process, including, but not limited to, the right to formal notice of violations, notice of an evidentiary hearing, the right to an evidentiary hearing, and a right to appeal. By entering into this Agreed Order, the Respondent agrees to waive all notice and procedural rights.

It is further understood and agreed that this Order represents the complete and fully-integrated settlement of the parties. The provisions of this Agreed Order are deemed severable and, if a court of competent jurisdiction or other appropriate authority deems any provision of this Agreed Order unenforceable, the remaining provisions shall be valid and enforceable. The duties and responsibilities imposed by this Agreed Order are binding upon the Respondent.

The Commission makes the following Findings of Fact and Conclusions of Law:

I. FINDINGS OF FACT

1. The Respondent owns and operates a petroleum refinery located at 1801 South Gulfway Drive in Port Arthur, Jefferson County, Texas (the "Plant").

2. The Plant consists of one or more sources as defined in TEX. HEALTH & SAFETY CODE § 382.003(12).
3. During an investigation conducted on May 6, 2014, TCEQ staff documented that the Respondent failed to prevent unauthorized emissions. Specifically, the Respondent released 110,224.70 pounds ("lbs") of sulfur dioxide, 3,270.70 lbs of volatile organic compounds, 28.80 lbs of particulate matter, 2,654.50 lbs of carbon monoxide, 367.60 lbs of nitrogen oxides, 1,195.90 lbs of hydrogen sulfide, and 109.70 lbs of ammonia during an emissions event (Incident No. 193520) that began on January 27, 2014 and lasted 5 hours and 20 minutes. These emissions were released from Emissions Point Numbers E-23-FLARE and E-26-FLARE. The event occurred when the Wet Gas Compressor K-6300 2nd Stage Anti-surge Valve tripped due to instrumentation failure. The trip was caused by an erroneous signal from Flow Transmitter ("FT") 30-FT-2806, which was due to a partial blockage of the FT manifold (high side only). The source of the blockage was suspected to be foreign debris and/or hydrate formation due to lack of adequate insulation aggravated by unusually cold winter weather. Since this event could have been avoided by better operational practices, the Respondent is precluded from asserting an affirmative defense under 30 TEX. ADMIN. CODE § 101.222.
4. The Respondent received notice of the violations on June 13, 2014.

II. CONCLUSIONS OF LAW

1. The Respondent is subject to the jurisdiction of the TCEQ pursuant to TEX. HEALTH & SAFETY CODE ch. 382 and Tex. Water Code ch. 7 and the rules of the Commission.
2. As evidenced by Findings of Fact No. 3., the Respondent failed to prevent unauthorized emissions, in violation of 30 TEX. ADMIN. CODE §§ 101.20(3), 116.115(b)(2)(F), 116.115(c), and 122.143(4), TEX. HEALTH & SAFETY CODE § 382.085(b), Federal Operating Permit No. 01498, Special Terms and Conditions No. 18, and New Source Review Permit Nos. 6825A, PSDTX49, and N65, Special Conditions No. 1.
3. Pursuant to TEX. WATER CODE § 7.051, the Commission has the authority to assess an administrative penalty against the Respondent for violations of the Texas Water Code and the Texas Health and Safety Code within the Commission's jurisdiction; for violations of rules adopted under such statutes; or for violations of orders or permits issued under such statutes.
4. An administrative penalty in the amount of Twenty-Five Thousand Dollars (\$25,000) is justified by the facts recited in this Agreed Order, and considered in light of the factors set forth in TEX. WATER CODE § 7.053. The Respondent has paid Twelve Thousand Five Hundred Dollars (\$12,500) of the administrative penalty. Twelve Thousand Five Hundred Dollars (\$12,500) shall be conditionally offset by the Respondent's completion of the Supplemental Environmental Project ("SEP").

III. ORDERING PROVISIONS

NOW, THEREFORE, THE TEXAS COMMISSION ON ENVIRONMENTAL QUALITY ORDERS that:

1. The Respondent is assessed an administrative penalty in the amount of Twenty-Five Thousand Dollars (\$25,000) as set forth in Section II, Paragraph 4 above, for violations of TCEQ rules and state statutes. The payment of this administrative penalty and the Respondent's compliance with all the terms and conditions set forth in this Agreed Order completely resolve the violations set forth by this Agreed Order in this action. However, the Commission shall not be constrained in any manner from requiring corrective actions or penalties for other violations that are not raised here. Administrative penalty payments shall be made payable to "TCEQ" and shall be sent with the notation "Re: The Premcor Refining Group Inc., Docket No. 2014-0903-AIR-E" to:

Financial Administration Division, Revenue Operations Section
Attention: Cashier's Office, MC 214
Texas Commission on Environmental Quality
P.O. Box 13088
Austin, Texas 78711-3088

2. The Respondent shall implement and complete the SEP in accordance with TEX. WATER CODE § 7.067. As set forth in Section II, Paragraph 4 above, Twelve Thousand Five Hundred Dollars (\$12,500) of the assessed administrative penalty shall be offset with the condition that the SEP defined in Attachment A, incorporated herein by reference, is implemented by the Respondent. The Respondent's obligation to pay the conditionally offset portion of the administrative penalty assessed shall be discharged upon final completion of all provisions of the SEP agreement.
3. The Respondent shall undertake the following technical requirements:
 - a. Within 30 days after the effective date of this Agreed Order, implement measures and/or procedures designed to prevent recurrence of emissions events due to similar causes as Incident No. 193520; and
 - b. Within 45 days after the effective date of this Agreed Order, submit written certification as described below, and include detailed supporting documentation including photographs, receipts, and/or other records to demonstrate compliance with Ordering Provision No. 3.a. The certification shall be notarized by a State of Texas Notary Public and include the following certification language:

"I certify under penalty of law that I have personally examined and am familiar with the information submitted and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the

information, I believe that the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fines and imprisonment for knowing violations."

The certification shall be submitted to:

Order Compliance Team
Enforcement Division, MC 149A
Texas Commission on Environmental Quality
P.O. Box 13087
Austin, Texas 78711-3087

with a copy to:

Air Section Manager
Beaumont Regional Office
Texas Commission on Environmental Quality
3870 Eastex Freeway
Beaumont, Texas 77703-1892

4. The provisions of this Agreed Order shall apply to and be binding upon the Respondent. The Respondent is ordered to give notice of the Agreed Order to personnel who maintain day-to-day control over the Plant operations referenced in this Agreed Order.
5. If the Respondent fails to comply with any of the Ordering Provisions in this Agreed Order within the prescribed schedules, and that failure is caused solely by an act of God, war, strike, riot, or other catastrophe, the Respondent's failure to comply is not a violation of this Agreed Order. The Respondent shall have the burden of establishing to the Executive Director's satisfaction that such an event has occurred. The Respondent shall notify the Executive Director within seven days after the Respondent becomes aware of a delaying event and shall take all reasonable measures to mitigate and minimize any delay.
6. The Executive Director may grant an extension of any deadline in this Agreed Order or in any plan, report, or other document submitted pursuant to this Agreed Order, upon a written and substantiated showing of good cause. All requests for extensions by the Respondent shall be made in writing to the Executive Director. Extensions are not effective until the Respondent receives written approval from the Executive Director. The determination of what constitutes good cause rests solely with the Executive Director.
7. The Executive Director may refer this matter to the Office of the Attorney General of the State of Texas ("OAG") for further enforcement proceedings without notice to the Respondent if the Executive Director determines that the Respondent has not complied with one or more of the terms or conditions in this Agreed Order.

8. This Agreed Order shall terminate five years from its effective date or upon compliance with all the terms and conditions set forth in this Agreed Order, whichever is later.
9. This Agreed Order, issued by the Commission, shall not be admissible against the Respondent in a civil proceeding, unless the proceeding is brought by the OAG to: (1) enforce the terms of this Agreed Order; or (2) pursue violations of a statute within the Commission's jurisdiction, or of a rule adopted or an order or permit issued by the Commission under such a statute.
10. This Agreed Order may be executed in separate and multiple counterparts, which together shall constitute a single instrument. Any page of this Agreed Order may be copied, scanned, digitized, converted to electronic portable document format ("pdf"), or otherwise reproduced and may be transmitted by digital or electronic transmission, including but not limited to facsimile transmission and electronic mail. Any signature affixed to this Agreed Order shall constitute an original signature for all purposes and may be used, filed, substituted, or issued for any purpose for which an original signature could be used. The term "signature" shall include manual signatures and true and accurate reproductions of manual signatures created, executed, endorsed, adopted, or authorized by the person or persons to whom the signatures are attributable. Signatures may be copied or reproduced digitally, electronically, by photocopying, engraving, imprinting, lithographing, electronic mail, facsimile transmission, stamping, or any other means or process which the Executive Director deems acceptable. In this paragraph exclusively, the terms "electronic transmission", "owner", "person", "writing", and "written" shall have the meanings assigned to them under TEX. BUS. ORG. CODE § 1.002.
11. The Chief Clerk shall provide a copy of this Agreed Order to each of the parties. By law, the effective date of this Agreed Order is the third day after the mailing date, as provided by 30 TEX. ADMIN. CODE § 70.10(b) and TEX. GOV'T CODE § 2001.142.

SIGNATURE PAGE

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

For the Commission


For the Executive Director

12/17/14
Date


I, the undersigned, have read and understand the attached Agreed Order in the matter of The Premcor Refining Group Inc. I am authorized to agree to the attached Agreed Order on behalf of The Premcor Refining Group Inc., and do agree to the specified terms and conditions. I further acknowledge that the TCEQ, in accepting payment for the penalty amount, is materially relying on such representation.

I understand that by entering into this Agreed Order, The Premcor Refining Group Inc. waives certain procedural rights, including, but not limited to, the right to formal notice of violations addressed by this Agreed Order, notice of an evidentiary hearing, the right to an evidentiary hearing, and the right to appeal. I agree to the terms of the Agreed Order in lieu of an evidentiary hearing. This Agreed Order constitutes full and final adjudication by the Commission of the violations set forth in this Agreed Order.

I also understand that failure to comply with the Ordering Provisions, if any, in this order and/or failure to timely pay the penalty amount, may result in:

- A negative impact on compliance history;
- Greater scrutiny of any permit applications submitted;
- Referral of this case to the Attorney General's Office for contempt, injunctive relief, additional penalties, and/or attorney fees, or to a collection agency;
- Increased penalties in any future enforcement actions;
- Automatic referral to the Attorney General's Office of any future enforcement actions; and
- TCEQ seeking other relief as authorized by law.

In addition, any falsification of any compliance documents may result in criminal prosecution.


Signature

9/24/14
Date

J. Greg Gentry
Name (Printed or typed)
Authorized Representative of
The Premcor Refining Group Inc.

VP + General Manager
Title

Instructions: Send the original, signed Agreed Order with penalty payment to the Financial Administration Division, Revenue Operations Section at the address in Section III, Paragraph 1 of this Agreed Order.

Attachment A
Docket Number: 2014-0903-AIR-E
SUPPLEMENTAL ENVIRONMENTAL PROJECT

Respondent:	The Premcor Refining Group Inc.
Penalty Amount:	Twenty-Five Thousand Dollars (\$25,000)
SEP Offset Amount:	Twelve Thousand Five Hundred Dollars (\$12,500)
Type of SEP:	Contribution to a Third-Party Pre-Approved SEP
Third-Party Administrator:	Texas Association of Resource Conservation and Development Areas, Inc.
Project Name:	<i>Tire Collection Events and Cleanup of Abandoned Tire Sites</i>
Location of SEP:	Jefferson County: Neches-Trinity Coastal River Basin, Gulf Coast Aquifer

The Texas Commission on Environmental Quality ("TCEQ") agrees to offset a portion of the administrative penalty amount assessed in this Agreed Order for the Respondent to contribute to a Supplemental Environmental Project ("SEP"). The offset is equal to the SEP Offset Amount set forth above and is conditioned upon completion of the project in accordance with the terms of this Attachment A.

1. Project Description

a. Project

The Respondent shall contribute the SEP Offset Amount to the Third-Party Administrator named above. The contribution will be to the **Texas Association of Resource Conservation and Development Areas, Inc. ("RC&D")** for the *Tire Collection Events and Cleanup of Abandoned Tire Sites* project. The contribution will be used in accordance with the SEP Agreement between the Third-Party Administrator and the TCEQ (the "Project"). Specifically, the SEP Offset Amount will be used to coordinate with local city and county government officials and private entities ("Partner Entities") to conduct tire collection events where residents will be able to drop off tires for proper disposal or recycling ("Collection Events"), or to clean sites where tires have been disposed of illegally ("Site Cleanups").

Texas RC&D shall ensure that collected tires, debris, and waste are properly transported to and disposed at an authorized disposal site, and if a licensed hauler is needed for tires or other regulated waste collected from sites, Texas RC&D shall ensure that only properly licensed haulers are used for transport and disposal of tires and regulated wastes. The SEP will be performed in accordance with all federal, state, and local environmental laws and regulations.

The Premcor Refining Group Inc.
Agreed Order - Attachment A

All dollars contributed will be used solely for the direct cost of the Project, including but not limited to supplies, materials, and equipment. Any portion of this contribution that is not able to be spent on the specifically identified SEP may, at the discretion of the Executive Director ("ED"), be applied to another pre-approved SEP.

The Respondent's signature affixed to this Agreed Order certifies that it has no prior commitment to make this contribution and that it is being contributed solely in an effort to settle this enforcement action. The Respondent shall not profit in any manner from this SEP.

b. Environmental Benefit

This SEP will provide an environmental benefit by providing communities with a free and convenient means for safe and proper disposal of tires and by reducing the dangers and health threats associated with illegally dumped tires.

The health risks associated with illegal dumping are significant. Areas used for illegal tire dumping may be easily accessible to people, especially children, who are vulnerable to the physical hazards posed by abandoned tires. Rodents, insects, and other vermin attracted to dump sites may also pose health risks. Tire dump sites which contain scrap tires pose an ideal breeding ground for mosquitoes, which can breed 100 times faster in the warm, stagnant water standing in scrap tire casings. Severe illnesses, including West Nile Virus, have been attributed to disease-carrying mosquitoes. The potential for tire fires is also reduced by removing illegally dumped tires. Tire fires can result in the contamination of air, surface water, ground water, and soil. In addition, neighborhoods have been evacuated and property damage has been significant due to tire dump sites that caught fire. Illegal tire dumping can also impact drainage of runoff, making areas more susceptible to flooding when wastes block waterways. Open burning at tire dump sites can cause forest fires and erosion as fires burn away trees and undergrowth. Tire dumping has a negative impact on trees and wildlife, and runoff from tire dumpsites may contain chemicals that can contaminate wells and surface water used for drinking.

c. Minimum Expenditure

The Respondent shall contribute at least the SEP Offset Amount to the Third-Party Administrator and comply with all other provisions of this SEP.

2. Performance Schedule

Within 30 days after the effective date of this Agreed Order, the Respondent must contribute the SEP Offset Amount to the Third-Party Administrator. The Respondent shall make the check payable to **Texas Association of RC&D SEP** and shall mail the contribution with a copy of the Agreed Order to:

The Premcor Refining Group Inc.
Agreed Order - Attachment A

Texas Association of RC&D Areas, Inc.
Attn.: Jerry Pearce, Executive Director
P.O. Box 2533
Victoria, Texas 77902

3. Records and Reporting

Concurrent with the payment of the SEP Offset Amount, the Respondent shall provide the Enforcement SEP Coordinator with a copy of the check and transmittal letter indicating full payment of the SEP Offset Amount to the Third-Party Administrator. The Respondent shall mail a copy of the check and transmittal letter to:

Texas Commission on Environmental Quality
Enforcement Division
Attention: SEP Coordinator, MC 219
P.O. Box 13087
Austin, Texas 78711-3087

4. Failure to Fully Perform

If the Respondent does not perform its obligations under this Attachment A, including full expenditure of the SEP Offset Amount, as described in Sections 2 and 3 above, the ED may require immediate payment of all or part of the SEP Offset Amount.

In the event the ED determines that the Respondent failed to fully implement and complete the Project, the Respondent shall remit payment for all or a portion of the SEP Offset Amount, as determined by the ED, and as set forth in the attached Agreed Order. After receiving notice of failure to complete the SEP, the Respondent shall include the docket number of the attached Agreed Order and a note that the enclosed payment is for the reimbursement of a SEP. The Respondent shall make the check payable to "Texas Commission on Environmental Quality" and shall mail it to:

Texas Commission on Environmental Quality
Litigation Division
Attention: SEP Coordinator, MC 175
P.O. Box 13087
Austin, Texas 78711-3087

5. Publicity

Any public statements concerning this SEP and/or project, made by or on behalf of the Respondent must include a clear statement that **the project was performed as part of the settlement of an enforcement action brought by the TCEQ**. Such statements include advertising, public relations, and press releases.

6. Clean Texas Program

The Respondent shall not include this SEP in any application made to TCEQ under the "Clean Texas" (or any successor) program(s). Similarly, the Respondent may not seek recognition for this contribution in any other state or federal regulatory program.

7. Other SEPs by TCEQ or Other Agencies

The SEP Offset Amount identified in this Attachment A and in the attached Agreed Order has not been, and shall not be, included as a SEP for the Respondent under any other Agreed Order negotiated with the TCEQ or any other agency of the state or federal government.